Figure 3-2   : Cm   xial ¤   qles   M

Figure 1-2: Uni-

1.2 Installation, HPAs to Frame

Warning: The base struts (Item 1) included in the mounting kit should be

1.3.2 C-Band Systems

The C-Band redundant system was shipped with the following components that comprise the waveguide switch array: a switch/termination assembly, switch support bracket, and waveguide segments that connect between the output of the HPAs and the switch. See **Figure 1-**

1

1.5 Installa &o   ll   nloll   l

1.6.1 Install M&C Cable

Th   f   M   h   h   h   s

1.7.1 Install Maintenance Switch Interface Panel

Install the maintenance switch interface panel to the uni-strut frame as shown in **Fe   rq   0**

2. Arrange the 20" sections of uni-strut (+   tÄ m) + rn mwo + r i e

Slide the switch assembly into the switch support bracket, making sure the baseball switch faces away from the uni-

215533

See **Fi   y**

1. Arrange the uni-strut sections (Items 1, 2, 3 and 5) as shown in **Figure 4-1**. Secure the 4-hole L-brackets (Item 12) on the flat side of the uni-

4.3 Installation, HPAs to Frame

215534 REV J